





Solder, Right Angle, and High Density Connectors				
01 = .120 dia. Riveted Front and Rear Shell	04 = Riveted #4-40 UNC Open Nuts on Rear Shell	05 = Riveted #4-40 UNC Closed Nuts on Front Shell	06 = Riveted #4-40 UNC Open Nuts on Front Shell	07 = Riveted #4-40 UNC Close Ground Stand-Off on Rear Shell (Stamped Contact)
07 = Riveted #4-40 UNC Close Ground Stand-Off on Rear Shell (Machined Contact)	08 = Riveted Ground Hooks with #4-40 UNC Open	09 = Riveted Ground Tabs with #4-40 UNC Open (Stamped Contact)	09 = Riveted Ground Tabs with #4-40 UNC Open (Machined Contact)	10 = Riveted Ground Hooks Pre-Loaded #4-40 UNC Hex Screws
11 = Assembly Ground Hooks By #4-40 UNC Hex Screws (Stamped Contact)	11 = Assembly Ground Hooks By #4-40 UNC Hex Screws (Machined Contact)	12 = Riveted #4-40 UNC Close Ground Stand-Off on Rear Shell (Stamped Contact) for High Profile Connectors	13 = Riveted #4-40 UNC Close Ground Stand-Off on Rear Shell (Stamped Contact)	CONSULT FACTORY FOR OTHER MOUNTING STYLES OPTION